



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah


DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Inspection Report Minerals Regulatory Program September 30, 2010

Reviewed: 

Mine Name: Anval 1-2	Permit Number: S0010038
Operator Name: Steven Gale	Inspection Date: 09/08/2010
Inspector(s): T Munson	Time: 2:30 PM
Other Participants: none	Mine Status: active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Permit fees: current

Bond: \$3,000

Purpose of Inspection: To conduct an annual inspection.


Inspection Summary:

The disturbance at this site has not changed since the last inspection. Several small pits exist for less than 1/2 acre of disturbance. There exists an old trackhoe that may or may not be operable. Photos were taken to document site conditions.

Conclusions and Recommendations:

The Division continue to do inspections of the site on an Annual basis.

Inspector's Signature



TM:eb

cc:

BLM ed-ginouves@blm.gov
O:\M001-Beaver\S0010038-Anval\inspections\insp-09082010.doc






Pit and trackhoe



Small pits



Old trackhoe



Small pits